## 4T40-E, 4T45-E

PART NUMBER 33886-03K

## Complaint

SECONDARY COMPLAINTS

## Cause

A worn boost valve sleeve allows torque signal and/or reverse pressure to cross leak or exhaust.

## CORRECTION

This replacement boost valve assembly restores hydraulic integrity to the circuits and properly controls line rise.

# **Boost Valve and Sleeve**

#### 33886-03K

1 Boost Valve

1 Sleeve

**Associated Parts** 

#### 33000-02

TCC Regulator Apply Sleeve




#### 33000-TL

- 1 Core Drill
- 1 Drill Guide
- 1 Reamer
- 1 Reamer Guide

### High or low line pressure

• Harsh or soft shifts • Delayed or no reverse



#### **Sonnax Part Summary**

The boost valve assembly is activated by torque signal pressure from the pressure control solenoid and reverse pressure to aid in adjusting line pressure at the pressure regulator valve. This boost valve is continuously oscillating in the sleeve, which leads to wear and hydraulic leakage. When wear occurs, critical oil pressure is allowed to cross-leak between the circuits or leak to exhaust. These leaks can result in either no line rise or an unwanted increase in line pressure. Sonnax now offers a replacement boost valve assembly 33886-03K that restores the hydraulic integrity and controls line rise.

#### **Features & Benefits**

- Replacement boost sleeve delivers oil 360° around the valve, reducing side load.
- Sleeve is manufactured from highly wear-resistant aluminum.
- Valve is made from anodized aluminum.
- Tight tolerances on the sleeve and valve maintain an ideal fit that prevents leakage.

Save

\$150 in valve body replacement costs

