PART NUMBER 37000-01K

# OMPLAINTDelayed engagements, elevated operating temperatures

SECONDARY COMPLAINT

## Cause

Spring failure, fatigue or miscalibration.

# <u>Correction</u>

Springs are made from improved material to reduce breakage. Converter relief and lube regulator spring have been calibrated to control converter charge and lube pressure.


### Lube Regulator & Converter Relief Valve Springs

### 37000-01K

1 Lube Regulator Valve Spring1.250"1 Converter Relief Valve Spring1.750"

**Notes:** These springs should be replaced as a pair, due to the pressure effects on each valve.

These springs work in 2003 & earlier units only. These units can be identified by counting the solenoids: The earlier units have 6 solenoids. Do not use in 2004 & up (7-solenoid) units.



### Sonnax Part Summary

The converter regulator spring controls converter charge and feeds the lubrication circuit. When the spring becomes weak or broken, converter pressure is reduced. This causes delayed engagements, reduced torque output and increased operating temperatures.

The lube regulator spring affects converter pressure as well as lubrication pressure within the cooler and unit. When this spring breaks or becomes fatigued, converter temperature and gear train temperatures increase.

If either spring is excessively strong, both converter and cooler pressure increases. This can result in converter flex and cooler circuit cross leakage.

### Features & Benefits

- Made from improved materials for increased durability over OEM.
- Drop-in replacement.
- Converter spring is recalibrated to improve converter charge and internal pressure.



