PART NUMBER 77010-01

# COMPLAINT

## Reaction carrier shaft damage

DARY COMPLAINT • Bushing failure

## CAUSE

Oil leakage due to inadequate support of the reaction sun gear.

## CORRECTION

The Sonnax sun gear bushing is more than one-and-a-half times as wide as the OEM and maximizes bushing support.

### Wide Reaction Sun Gear Bushing

### 77010-01

1 Wide Reaction Sun Gear Bushing



### **Sonnax Part Summary**

The Sonnax replacement bushing 77010-01 is one-and-a-half times the width of the OEM version and fills the entire sun gear bushing groove. This wider bushing maximizes support. The bushing is steel-backed bronze that is precision machined to provide minimal clearance with the mating shaft.

#### **Features & Benefits**

- Provides better control of lube oil.
- Has more support for sun gear and reaction shell.
- Greater longevity than OE bushing.

