

COMPLAINT

Excessive front unit endplay

CAUSE

Normal wear of shim.


CORRECTION

This .015" shim installs between the front input OEM selective and the drum pocket and allows for quick set-up and adjustment when excessive end-play has been determined.

Stator to Input Housing Shim

77409-15

10 Front Unit Endplay Shims .0160"



Sonnax Part Summary

Sonnax has designed a shim 77409-15 (.015" thick) to better help the needs of the rebuilder in the selection of shims when checking for front unit endplay. This .015" shim was designed to be placed between the front input OEM selective and the drum pocket. This allows for quick set-up and adjustment when excessive endplay has been determined.