

COMPLAINT

3-4 Clutch boost springs collapse and are ineffective once they have been overheated.

CAUSE

Springs collapse and lose strength when overheated due to 3-4 clutch failure.


CORRECTION

Install these precision manufactured, direct replacement boost springs.

3-4 Clutch Boost Spring

77763-01

10 Boost Springs



Sonnax Part Summary

The 77763-01 boost springs offer a low cost, direct replacement alternative to the OE springs. Engineered for the application, the 77763-01 boost springs are precision manufactured from high quality spring materials.

Features & Benefits

- Low-cost direct replacement
- Precision manufactured
- Made from high quality spring material.