

COMPLAINT

SECONDARY COMPLAINTS

Misalignment or damage to the transmission case

- Pump noise • Seal leaks • Bushing and converter hub wear

CAUSE

The thin wall construction of the OEM pins is not durable enough.

CORRECTION

Replace with these case dowel pins that have a thicker wall.


Case Dowel Pins

85000-01

6 Case Dowel Pins



Case Dowel Pin



Sonnax Part Summary

A common problem with OEM case dowel pins for the ZF5HP30 is weak construction, which results in misalignment or damage to the transmission case. The Sonnax dowel pin **85000-01** is a more durable guide pin between the engine block and transmission case, preventing the misalignment that can occur with the OEM guide pins.