### **41TE** ('94 TO '97 W/INTERNAL BYPASS VALVE)

PART NUMBER 92836-01K

# COMPLAINT

SECONDARY COMPLAINTS

## CAUSE

The cooler bypass valve may be stuck open, reducing converter apply pressure.

## CORRECTION

This bypass plug disables the OEM bypass valve and directs all fluid through the cooler.


### **Bypass Plug**

#### 92836-01K

2 Bypass Plugs

### Lockup shudder, low cooler flow

• Erratic switch codes • Soft, long 1-2 shift • Erratic coastdown bumps • Converter clutch slippage



#### **Sonnax Part Summary**

Chrysler 41TE units ('94 to '97 w/internal bypass valve) includes a bypass valve in the transmission case. The intent of the bypass valve is to re-route ATF flow from the cooler to the lube circuit if (and only if) there is a blockage in the cooler. Often, the OEM bypass becomes stuck in the open position due to wear or contamination. With the bypass valve constantly open, much of the ATF does not pass through the cooler. This can lead to overheating. Also, with the bypass valve stuck open, fluid pressure is relieved from the system. If the pump volume cannot replace the relieved pressure, then system pressure will remain low and lead to converter clutch slippage.

#### **Features & Benefits**

• Cooler flow can be restored without removing unit from vehicle.



On R&R and teardown labor time

**Note:** Previous Sonnax instructions indicated that the **92836-01K** could be used in 42LE applications. It has come to our attention that many (especially late model) 42LE cases were not drilled consistently and will not accept the bypass plug.

