4L60-E, 4L65-E

AFL END PLUG

Features & Benefits:

• Direct replacement



Part No. 77754-39

5 AFL End Plugs



PART SUMMARY

The end plug at the AFL (actuator feed limit) valve is often lost or damaged during valve body inspection or service. Sonnax now offers a direct replacement end plug, 77754-39, for this location.

©2007 Sonnax® Industries, Inc. 77754-39 07-03-07