




VBX-ValveBody **Xpress**™

5R55N



***** PLEASE NOTE *****

This Valve Body is available with or without an OEM Solenoid Pac.
A defective Solenoid Pac can produce multiple fault codes.

Both VBX and the manufacturer **HIGHLY RECOMMEND** that
this Solenoid Pac be replaced whenever a transmission problem
or failure occurs.

1-866-2GET-VBX

(1-866-243-8829)

www.valvebodyxpress.com

5R55N (Without Solenoid Pac) - **VBX** Part # F030

5R55N (WITH Solenoid Pac) - **VBX** Part # F031

"We Build Them So You Don't Have To."™