

Jatco

RE5R05A*

*The solutions here fit Nissan, Infinity RE5R05A and Kia A5SR1/A5SR2.

sonnax®

TIME TESTED • INDUSTRY TRUSTED®

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

- ① **63741-05K** 1st & 2nd Design Only
**TCC Control Valve Kit/Low
Brake Switch Boost Valve Kit**

- ② **63741-25K** 3rd & 4th Design Only
TCC Control Plunger Valve Kit

Helps cure:

- Lockup shudder
- TCC cycling
- Burnt converters

- ③ **63741-17K**
TC Regulator Valve Kit

Helps cure:

- Converter related complaints & codes
- Damaged TCC linings
- Lube failures

Note: Requires tool kit **F-63741-TL13**
& the **VB-FIX** reaming fixture.

- ④ **63741-01K**
**Oversized Pressure
Regulator & Boost
Valve Kit**

Helps cure:

- High line pressure
- Reduced converter & lube flow
- Delayed Forward/harsh Reverse


Note: Requires tool kit **F-63741-TL**
& the **VB-FIX** reaming fixture.

- ⑤ **63741-13K**
“A” or “B” Pilot Valve Kit

Helps cure:

- Delayed engagements
- Erratic shifts
- Linear solenoid codes

Note: Requires tool kit **F-63741-TL13**
& the **VB-FIX** reaming fixture.



- ⑥ **63741-20K**
**Accumulator Control
Valve Kit**

Helps cure:

- Shift feel complaints
- Shift feel related codes


Note: Requires tool kit **F-63741-TL13**
& the **VB-FIX** reaming fixture.

- ⑦ **63741-07K**
**Oversized Cooler
Bypass Valve Kit**

Helps cure:

- Fluid overheating
- Diminished lubrication
- Burnt hard parts/planetaries/converters

Note: Requires tool kit **F-63741-TL7**
& the **VB-FIX** reaming fixture.



Cooler bypass
valve not used
in all models.