JF506E, VW AG5/ 09A

PART NUMBERS 122892-03K, F-122892-TL3

COMPLAINT

SECONDARY COMPLAINTS

Cause

A worn pressure regulator bore and valve.

CORRECTION

The Sonnax pressure regulator kit salvages worn valve bodies by restoring the hydraulic integrity of the pressure regulator circuits.

Oversized Pressure Regulator Valve Kit

122892-03K

- 1 Valve
- 1 Spring
- 1 End Plug




F-122892-TL3

- 1 Reamer
- 1 Reamer Jig
- 1 Guide Pin

Note: These valve and tool kits also service Jatco FP series; Ford JF506E, FPH; Jaguar JF506E, FPD; Mazda JA5A-EL FPF1/FPF2; Rover JF506E, FPO; and Nissan ZY units.

Erratic pressure

• Delayed engagements • Loss of lockup • Low line in drive range • High pressure in reverse



Sonnax Part Summary

Constant movement of the pressure regulator valve wears the valve body bore. Bore/valve wear causes erratic line pressure, resulting in delayed engagements, loss of lockup and high or low line pressure, depending on the area and extent of wear. Sonnax offers a highly wear-resistant valve assembly, 122892-03K. Use of this kit allows the valve body bore to be resized, salvaging expensive cores.

Features & Benefits

- Kit includes an oversized, hard-anodized valve, calibrated pressure spring and oversized end plug.
- Tool kit provides an efficient and economic in-shop repair of worn valve bodies.

