




# 400, 4L80-E

## FORWARD CLUTCH HUB WASHERS (FRONT)

H I G H   P E R F O R M A N C E   T R A N S M I S S I O N   P A R T S

### FEATURES & BENEFITS

- Forward hub washers are .015" thicker than OEM
- Installation between the forward drum and forward clutch hub reduces front unit endplay



### Part No.

**34298-078**

*5 Washers, .078" Thick*

### PART SUMMARY:

Sonnax forward clutch hub washer **34298-078** is .015" thicker than the OEM version and replaces the OEM .063" thick washer between the forward clutch hub and the forward drum. This allows front unit endplay to be reduced. This new washer is an alternative to the Sonnax washers, **34301-078** and **-094**. Shimming at this location maintains the relationship with the forward clutch hub and direct drum and does not alter the endplay path through the unit.