

## COMPLAINT

No upshift, low line rise

## CAUSE

Worn and scored governor bores.


## CORRECTION

This replacement sleeve provides a new surface for the rings to seal properly.

## Governor Bore Sleeve

**69835**

1 Governor Bore Sleeve



### Sonnax Part Summary

The governor sleeve on the RL4R01A case wears and becomes scored. After the sleeve is worn excessively, the case has to be replaced. Sonnax now offers a replacement sleeve **69835** that allows the rebuilder to reuse cases with worn governor sleeves.

### Features & Benefits

- Replacement sleeve is made from high-quality material to resist wear.
- Salvages costly cases.