

**COMPLAINT**

Soft shifts

**CAUSE**

Inadequate accumulator piston control due to low rate or broken spring.


**CORRECTION**

This spring has performance specifications to match the purple OEM accumulator spring.

**1-2 or 3-4  
Accumulator  
Spring – Purple**

**74926**

Accumulator Spring



**Sonnax Part Summary**

Sonnax now offers a replacement spring **74926** for use in the 1-2 or 3-4 accumulator of the 4L60 and 4L60-E transmissions. The Sonnax spring has identical performance specifications to the purple OEM accumulator spring. The Sonnax spring uses high strength spring wire to ensure lasting spring life and reduce spring relaxation.