




5R55S/W



\*\*\* PLEASE NOTE \*\*\*

This Valve Body is available with or without an OEM Solenoid Pac.  
A defective Solenoid Pac can produce multiple fault codes.

Both VBX and the manufacturer **HIGHLY RECOMMEND** that  
this Solenoid Pac be replaced whenever a transmission problem  
or failure occurs.

1-866-2GET-VBX  
(1-866-243-8829)

[www.valvebodyxpress.com](http://www.valvebodyxpress.com)

5R55S/W (Without Solenoid Pac) - VBX Part # F032

5R55S/W (WITH Solenoid Pac)- VBX Part # F034

*"We Build Them So You Don't Have To."*