

## PART SUMMARY

Vehicles equipped with the Mercedes 722.6 transmission may have premature planetary failure due to poor lubrication. Sonnax now offers **68410-02K**, a needle bearing & seal kit for the K2 clutch drum. This kit can save you up to \$300 in planet replacement costs.