

COMPLAINT

Lost, damaged or modified original valve

CAUSE

Many throttle valves have been modified or replaced with a kit version during previous rebuilds. This often alters performance, rendering the core unusable.

CORRECTION

This direct replacement throttle valve aids in restoring the core to original condition by following the OEM design.

Direct Replacement Throttle Valve

77968-02

1 Throttle Valve

Also Available

77966-93K OEM 93

77966-94K OEM 94

77966-94MK High Performance

Each kit includes the following

- 1 Plunger
- 1 Sleeve
- 1 Spring

Note: 77966-94MK allows full throttle upshifts from 3rd gear to overdrive.


77968

Oversized Throttle Valve



77968-RM

1 Reamer



Sonnax Part Summary

Modifying or replacing the throttle valve is a common practice during rebuild, but these modifications and replacements often alter performance, leaving the core unusable. The Sonnax replacement throttle valve aids in restoring the core to original condition by following the OEM design.

Features & Benefits

- Valve is made from hardened steel.
- Follows OEM design.
- Salvages cores.