41TE, 42LE

PART NUMBER 92834-02K

COMPLAINT

SECONDARY COMPLAINTS

CAUSE

The steel clutch plate lugs wear grooves into the aluminum case and interrupt smooth clutch apply/release.

Correction

Channel inserts provide a smooth surface, eliminating plate hang-up.

Low-Reverse Clutch Channel Insert Kit

92834-02K

- 13 Channel Inserts
- 5 Steel Clutch Plates
- 5 Friction Clutch Plates
- 1 Insert Retaining Ring

Intermittent low/reverse clutch apply/release problems

• No forward or reverse • Burned low/reverse clutch • Harsh 2-1 downshifts • Destroyed cases



Sonnax Part Summary

Hardened spring steel inserts fit into the damaged case channels. The steel plates included with the kit have unique lugs that are narrower than the OEM to allow clearance at the installed inserts. Alto® clutch friction plates are included with the kit, although any OEM or quality aftermarket friction plates for the application will function with the special steels. Fits the low reverse clutch only.

Features & Benefits

- Saves cases with worn or damaged channels.
- Kit comes complete with inserts, frictions, steels and retainer.

