




48RE (2003 & Up)



The 48RE has no vent hole in the above indicated location, (see **RED ARROW**).

1-866-2GET-VBX

(1-866-243-8829)

www.valvebodyxpress.com

48RE (2003 & Up) - **VBX** Part # CHR133

"We Build Them So You Don't Have To."™