




## 4L60E (1995) No Tab on 3-2 DS & EPC Cast



The 1995 is a 1 Year Only!!  
To identify, the 3-2 Downshift Solenoid  
WILL NOT HAVE A TAB (See **GREEN ARROW**).  
You can also check the year, located by the Casting Stamp  
near the EPC Solenoid (See **RED ARROW**).  
A 1995 Valve Body should be stamped "95."

**1-866-2GET-VBX**

(1-866-243-8829)

[www.valvebodyxpress.com](http://www.valvebodyxpress.com)

4L60E (1995) - **VBX** Part # GM047

***"We Build Them So You Don't Have To."***